

Radon Inspection Report

Measurement of Radon Concentration in Indoor Air

Report No.: 2700005696201905251809
 Serial No.: 2700005696

Report Generated Date: 5/25/19

Measurement Address:

XXXX XXXX XXX XX
 Hartsel , CO 80440
 United States

Measurement performed by:

Kirk A . Stanley
 Sky Seals LLC
 PO Box 1589
 FAIRPLAY , Co 80440
 Info@skyseals.com
 USA

Ventilation: Balanced

Building type: House

Building year: 2008

Room	Floor	Measurement Start	Measurement End	Measured Value
Basement	Basement	5/23/19, 8:40 AM	5/25/19, 8:40 AM	5.0 pCi/L

Hartsel

Location

May 25, 2019

Date



Signature

Detailed Measurement Data


	Min	Max	Average
Radon [pCi/L]	1.7	8.6	5.0
Temperature [°F]	49.6	62.2	52.6
Humidity [%rH]	30	33	31
Pressure [kPa]	68.12	68.74	68.45

Radon measurements for hour 1 to hour 48


Hour	Radon conc. [pCi/L]
5/23/19, 8:40 AM	3.0
5/23/19, 9:40 AM	2.4
5/23/19, 10:40 AM	4.4
5/23/19, 11:40 AM	3.4
5/23/19, 12:40 PM	1.7
5/23/19, 1:40 PM	4.1
5/23/19, 2:40 PM	7.1
5/23/19, 3:40 PM	5.7
5/23/19, 4:40 PM	5.1
5/23/19, 5:40 PM	3.7
5/23/19, 6:40 PM	4.0
5/23/19, 7:40 PM	7.1
5/23/19, 8:40 PM	5.7
5/23/19, 9:40 PM	6.7
5/23/19, 10:40 PM	7.7
5/23/19, 11:40 PM	5.4
5/24/19, 12:40 AM	7.0
5/24/19, 1:40 AM	6.6
5/24/19, 2:40 AM	4.3
5/24/19, 3:40 AM	5.0
5/24/19, 4:40 AM	6.6
5/24/19, 5:40 AM	4.0
5/24/19, 6:40 AM	4.6
5/24/19, 7:40 AM	3.6

Hour	Radon conc. [pCi/L]
5/24/19, 8:40 AM	7.3
5/24/19, 9:40 AM	5.3
5/24/19, 10:40 AM	5.3
5/24/19, 11:40 AM	3.0
5/24/19, 12:40 PM	4.9
5/24/19, 1:40 PM	4.9
5/24/19, 2:40 PM	5.3
5/24/19, 3:40 PM	5.3
5/24/19, 4:40 PM	8.6
5/24/19, 5:40 PM	7.0
5/24/19, 6:40 PM	4.6
5/24/19, 7:40 PM	5.9
5/24/19, 8:40 PM	3.6
5/24/19, 9:40 PM	6.3
5/24/19, 10:40 PM	3.9
5/24/19, 11:40 PM	3.9
5/25/19, 12:40 AM	4.0
5/25/19, 1:40 AM	5.0
5/25/19, 2:40 AM	2.6
5/25/19, 3:40 AM	3.9
5/25/19, 4:40 AM	4.6
5/25/19, 5:40 AM	4.9
5/25/19, 6:40 AM	5.3
5/25/19, 7:40 AM	5.9

Radon Chart



Humidity and Temperature Chart



Pressure Chart

